



ACO Drain

KlassikDrain KS200

PORTFOLIO

### AC Baths Taupo

At the end of 2020 the AC Baths in Taupo have gone through a repair project for the indoor pools. Very aged existing drainage was no longer fit for purpose and had to be replaced. Therefore our sloping KlassikDrain KS200 together with stainless steel 5 Star **Heelsafe**® Anti-Slip grates were installed to capture the surface water along the pools. The new drains had to be easy to maintain and drain completely which is why a sloping system was essential. Especially for pool applications, it's important no ponding occurs and grates won't allow for any slipping hazards keeping visitors safe. Upon completion further KS200 drains were installed to improve drainage around some external pools.



### Benefits

- ACO's KlassikDrain KS200 with Stainless Steel 5 Star **Heelsafe**® Anti-Slip grates, providing visitor safety surface water management.
- Recesses in the edge rail fit around 'anti-shunt' lugs on the grate to prevent longitudinal movement.
- No end bars for visual continuity.
- Certified to AS 3996 Load Class B (80kN)



[www.aconz.co.nz](http://www.aconz.co.nz)

